

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
DEL,
3-MILF,
2-

Causey House
2 Causey Avenue
Milford
Sussex County
Delaware

DE-183

Documentation: 10 exterior photos (1982)
1 data page (1983)

Jack E. Boucher, Photographer July, 1982

DE-183-1 NORTHEAST FRONT FROM NORTH

DE-183-2 NORTHEAST FRONT FROM EAST

DE-183-3 SOUTHEAST WING, SOUTHEAST AND NORTHEAST SIDES

DE-183-4 SOUTHEAST WING, NORTHEAST FRONT

DE-183-5 NORTHWEST END

DE-183-6 NORTHEAST FRONT, DETAIL OF DOORWAY

DE-183-7 NORTHEAST FRONT, DETAIL OF RAILING ON ENTRANCE PORCH

DE-183-8 NORTHEAST FRONT, DETAIL OF WINDOW

DE-183-9 NORTHEAST FRONT, DETAIL OF ATTIC WINDOW

DE-183-10 SLAVE QUARTERS